


## What is FATIGUE ?

- Most machine elements are subjected to **varying or fluctuating** stresses due to movement such as shafts, gears, bearings, cams and followers, etc.
- Fluctuating loads **repeated over long period of time** will cause a part to fail (fracture) at stress level **much smaller** than the **ultimate strength** or even the **yield strength** in some cases.
- Fatigue failure is somehow similar to brittle fracture where the fracture surfaces are **perpendicular** to the load axis.
- In general, fatigue failure develops in three stages:
  - **Stage1:** development of one or more **micro cracks** (size of two to five grains) due to the cyclic local plastic deformation.
  - **Stage2:** the cracks progress from **micro to macro** scale and keep growing making a smooth plateau-like fracture surface with beach marks.
  - **Stage3:** occurs during the final stress cycle where the remaining material cannot support the load resulting in **sudden fracture**.



- Fatigue failure is due to crack formation and propagation. Fatigue cracks usually initiate at location with high stresses such as **discontinuities** (hole, notch, scratch, sharp corner, etc.)
- Fatigue cracks can also initiate at surfaces having **rough surface** finish or due to the presence of tensile **residual stresses**. Thus all parts subjected to fatigue loading are **heat treated and polished** in order to increase the fatigue life.

## Fatigue Life Methods


- There are three major fatigue life methods: the **stress-life** method, the **strain-life** method and the **linear elastic fracture mechanics** method. Each one of these methods is more accurate for types of loading or for some materials.
- The fatigue life is usually classified according to the **number of loading cycles** into:
  - Low cycle fatigue ( $1 \leq N \leq 1000$ ) and for this low number of cycles, designers sometimes **ignore** fatigue effects and just use static failure analysis.
  - High cycle fatigue ( $N > 1000$ ):
    - Finite life**: from  $10^3$  to  $10^6$  cycles
    - Infinite life**: more than  $10^6$  cycles

## The strain-Life Method

- The fatigue life is related to the **amount of plastic strain** suffered by the part during the repeated loading cycles.
- If the stress direction is reversed (from tension to compression), the yield strength in the reversed direction will be smaller than its initial value which means that the material has been **softened** in the reverse direction.
- The strain-life is applicable to **Low-cycle fatigue**.


## The Linear Elastic Fracture Mechanics Method

- This method assumes that a crack initiates in the material and it keeps growing until failure occurs (the three stages described before)
- The LEFM approach assumes that a small crack **already exists** in the material, and it **calculates** the number of loading cycles required for the crack to grow enough to cause complete fracture.
- This method is more **applicable** to High-cycle fatigue.



## The stress-Life Method

- This method relates the **fatigue life to the alternating stress level** causing failure but it does not provide explanation to why failure happens. .
- The stress-life relation is obtained experimentally using Moore high speed **rotating beam test**.
  - The data obtained from the tests is used to generate the **fatigue strength vs. fatigue life** diagram which is known **S-N diagram**.
  - The first point is the ultimate strength which corresponds to **failure in half a cycle**.
  - The alternating stress amplitude is **reduced** below the ultimate strength and the test run until failure. The stress level and number of cycles until failure give a data point on the chart.
  - for steel alloys, the low cycle fatigue and the high cycle fatigue (finite and infinite) can be recognized as having different slopes.
  - for steel, with reducing the stress amplitude, we will reach to a stress for which the specimen will never fail, and this stress value is known as the Endurance Limit ( $S_e$ )



- The number of stress cycles associated with the **Endurance Limit** defines the boundary between **Finite** life and **infinite** life, and it is usually between  $10^6$  to  $10^7$  cycles.
- Steel and titanium alloys have a clear endurance limit, but this is not true for all materials.
  - For instance, Aluminium alloys do not have an endurance limit and for such materials the fatigue strength is reported at  $5(10^8)$  cycles.
  - Also, most polymers do not have an endurance limit

## Endurance Limit

- It is important to **sure** that the fatigue stress level in the element is **below** the endurance limit of the material being used.
- The relation between the endurance limit and ultimate strength for steel is given as:

$$S'_e = \begin{cases} 0.5S_{ut} & S_{ut} \leq 1400 \text{ MPa} \\ 700 \text{ MPa} & S_{ut} > 1400 \text{ MPa} \end{cases}$$

The prime (') is used to denote that this is the endurance limit value obtained for the test specimen.

## Endurance Limit Modifications Factors

- Some **modifications factors** are used to correlate the endurance limit for a given mechanical element to the value obtained from tests.

$$S_e = k_a k_b k_c k_d k_e k_f S_e'$$

Size    Temp.    Misc.  
 ↓       ↓       ↓  
 $S_e = k_a k_b k_c k_d k_e k_f S_e'$   
 ↑       ↑       ↑  
 Finish    Load    Reliability

$S_e$  : the endurance limit at the critical location of a **machine element** with the geometry and conditions of use.

$S_e'$  : the endurance limit obtained from the rotating beam test.

$k_a \dots k_f$  : Modification factors (obtained experimentally)

### ✓ Surface Condition Factor ( $k_a$ )

- The rotating beam test specimens are highly polished. A **rough surface** finish will **reduce the endurance limit** because there will be a higher potential for crack initiation.

- The surface condition modification factor depends on the **surface finish** of the part (ground, machined, as forged, etc.) and on the tensile strength of the material. It is given as:

$$k_a = aS_{ut}^b$$

Constants  $a$  and  $b$  depend on surface condition and are given in the below table.

Surface Finish	Factor $a$		Exponent $b$
	$S_{ut}$ , kpsi	$S_{ut}$ , MPa	
Ground	1.34	1.58	-0.085
Machined or cold-drawn	2.70	4.51	-0.265
Hot-rolled	14.4	57.7	-0.718
As-forged	39.9	272.	-0.995

## ✓ Size Factor ( $k_b$ )

- The rotating beam specimens have a specific small diameter. Parts of larger size are more likely to contain flaws and to have more non-homogeneities. The size factor is given as:

For bending and torsion

$$k_b = \begin{cases} 1.24 d^{-0.107} & 2.79 \leq d \leq 51\text{mm} \\ 1.51 d^{-0.157} & 51 < d \leq 254\text{mm} \end{cases}$$

❖ where  $d$  is the diameter

For axial loading

$$k_b = 1$$

*for rotating shaft*

- When a circular shaft is **not rotating** we use an **effective diameter** value instead of the actual diameter, where

$$d_e = 0.37 d$$

- A rectangular section of dimensions  $h \times b$  has  $d$  value as:

$$d = 0.808(h \times b)^{1/2}$$

- ❖ and for nonrotating rectangular shaft, the effective diameter strategy is utilized

## ✓ Loading Factor ( $k_c$ )

- The rotating beam specimen is loaded in **bending**. Other types of loading will have a different effect.
- The load factor for the **different types of loading** is:

$$k_c = \begin{cases} 1 & \text{bending} \\ 0.85 & \text{axial} \\ 0.59 & \text{torsion} \end{cases}$$

## ✓ Temperature Factor ( $k_d$ )

- When the operating temperature is **below room temperature**, the material becomes **more brittle**. When the **temperature is high** the yield strength decreases and the material becomes **more ductile** and creep may occur.
- For steel, the endurance limit slightly increases as temperature rises, then it starts to drop. Thus, the temperature factor is given as:

$$k_d = 0.9887 + 0.6507(10^{-3})T_c - 0.3414(10^{-5})T_c^2 + 0.5621(10^{-8})T_c^3 - 6.426(10^{-12})T_c^4$$

- The same value calculated by the equation are also presented in the below table where :

$$k_d = \frac{S_T}{S_{RT}}$$

Temperature, °C	$S_T/S_{RT}$	Temperature, °F	$S_T/S_{RT}$
20	1.000	70	1.000
50	1.010	100	1.008
100	1.020	200	1.020
150	1.025	300	1.024
200	1.020	400	1.018
250	1.000	500	0.995
300	0.975	600	0.963
350	0.943	700	0.927
400	0.900	800	0.872
450	0.843	900	0.797
500	0.768	1000	0.698
550	0.672	1100	0.567
600	0.549		

## ✓ Reliability Factor ( $k_e$ )

- The **mean** endurance limit is shown to be  $Se'/S_{ut} = 0.5$ . Most **endurance strength** data are reported as **mean values**.
- Data presented by Haugen and Wirching show standard **deviations** of endurance strengths of less than **8%**.
- For other values of reliability,  $k_e$  is found from the table given here.

Reliability, %	Transformation Variate $z_a$	Reliability Factor $k_e$
50	0	1.000
90	1.288	0.897
95	1.645	0.868
99	2.326	0.814
99.9	3.091	0.753
99.99	3.719	0.702
99.999	4.265	0.659
99.9999	4.753	0.620

## ✓ Miscellaneous Factor ( $k_f$ )

- It is used to account the reduction in the endurance limit due to all other effects (such as residual stress, corrosion, cyclic frequency, metal spraying, etc.)
- However, these effects are not fully characterized and usually not accounted for. Thus we use  $k_f = 1$ .

## ✓ Stress concentration and notch sensitivity.

- Under fatigue loading conditions, crack initiation and growth usually starts in locations having high stress concentrations.
- The presence of stress concentration **reduces** the fatigue life of an element and the endurance limit as well and it must be considered in fatigue failure analysis.
- Due to the **difference in ductility**, the effect of stress concentration on fatigue properties is not the same for different materials.
- For materials under fatigue loading, the maximum stress near a notch (hole, fillet, etc.) is:

$$\sigma_{max} = k_f \cdot \sigma_o \quad \text{or} \quad \tau_{max} = k_{fs} \cdot \tau_o$$

❖ where:  $\sigma_o$ : the nominal stress.

$k_f$ : the fatigue stress concentration factor which is a reduced value of the stress concentration factor ( $k_t$ ) because of the difference in material sensitivity to the presence of notches.

and  $k_f$  is defined as:

$$k_f = \frac{\text{max. stress in notched specimen}}{\text{stress in notch-free specimen}}$$

- **Notch sensitivity** ( $q$ ) is defined as:

$$q = \frac{k_f - 1}{k_t - 1} \quad \text{or} \quad q_{shear} = \frac{k_{fs} - 1}{k_{ts} - 1}$$

- ❖ The values of  $q$  ranges from 0 to 1
  - $q=0 \rightarrow k_f=1$  material is not sensitive
  - $q=1 \rightarrow k_f=k_t$  material is fully sensitive

- ❖ Thus

$$k_f = 1 + q(k_t - 1) \quad \text{or} \quad k_{fs} = 1 + q_s(k_{ts} - 1)$$

- ❖ For steels and Aluminum, the notch sensitivity for **Bending and Axial** loading can be found from figure A and for **Torsion** is found from Figure B.
- ❖ For cast iron, the notch sensitive is very low from 0 to 0.2, but to be conservative it is recommended to use  $q=0.2$ .




Figure A




Figure B

- Heywood distinguished between **different types of notches** (hole, shoulder, groove) and according to him,  $k_f$  is found as:

$$k_f = \frac{k_t}{1 + \frac{2(k_t - 1)\sqrt{a}}{k_t\sqrt{r}}}$$

- ❖ Where,  $r$  : radius  
 $\sqrt{a}$  : constant that depends on the type of the notch.
- ❖ For steels,  $\sqrt{a}$  for different types of notches is given in the table below.

Notch Type	$\sqrt{a}(\sqrt{\text{in}})$ , $S_{ut}$ in kpsi	$\sqrt{a}(\sqrt{\text{mm}})$ , $S_{ut}$ in MPa	Coefficient of Variation $C_{Kf}$
Transverse hole	$5/S_{ut}$	$174/S_{ut}$	0.10
Shoulder	$4/S_{ut}$	$139/S_{ut}$	0.11
Groove	$3/S_{ut}$	$104/S_{ut}$	0.15

- For **simple loading**,  $k_f$  can be **multiplied** by the stress value, or the endurance limit can be reduced by **dividing** it by  $k_f$ . However, for **combined loading** each of stress has to be multiplied by its corresponding  $k_f$  value.